

VHF Receiver Mother Board Assembly 400075-46-1

The VHF Receiver mother board 400075-46-1 is used in all DF2100 VHF receivers. It is a direct replacement for the wire wrapped assy 400075-46 that is no longer available. It comes with all cables and connectors attached. The user does not have to solder or wire anything. The board can be installed in the field in about 2-3 hrs. There is no electrical alignment or tuning needed. The only tool needed is the screwdriver. Depending on the option the connectors for A10, A11 or A13 boards can be installed.




Fig.1 DF2100 VHF Receiver Mother Board 400075-46